

Report on the control column.

Based on the information of July 24, 2023 regarding the possibility of cracks in the welded joint at the attachment points of control column, left to the control stick, in the elevator control system, on the Swift glider, the jury of the FAI WORLD GLIDER AEROBATIC CHAMPIONSHIP 13th FAI WORLD ADVANCED GLIDER AEROBATIC CHAMPIONSHIP decided to check the above-mentioned tiller by a committee, based on the points from the bulletin No. BO-112/ 2005 SWIFT S-1 on all SWIFT S-1 gliders taking part in the competition:

- OE 5554;
- OK 2100;
- OK 2151;
- D 5542;
- D 3168;
- D 7125;
- D 3735;
- D 8139;
- D 9590;
- HA 7022;
- SP 3529;
- SP 3532.

On July 25, 2023 the above-mentioned gliders, before the next flights had visual inspection of the control column for cracks and damage.
The test result for all gliders was positive.

Committee:

	Name and surname	Signature function
1.	Stanisław Kozut	1. Technical Committee
2.	Dariusz Warchochi	2. Technical Committee
3.	MICHAEL KAISEN	3. Technical Committee
4.	Peter S. [Signature]	4.